

EAST Search History

EAST Search History (Prior Art)

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	4	("20040181174" "5465732" "5746701" "6139511").did.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; IBM_TDB	OR	ON	2009/08/18 10:10
S1	13	crank-justin.in.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/01/06 09:43
S3	1362	600/585.ccls. and @ad<"20030825"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/01/06 09:58
S4	780	600/585.ccls. and @ad<"20030825" and coil	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/01/06 09:59
S5	581	600/585.ccls. and @ad<"20030825" and coil and taper\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/01/06 09:59
S6	122	600/585.ccls. and @ad<"20030825" and coil and taper\$4 and composite	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/01/06 10:12
S7	970	(guidewire stent) and clad \$	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/01/06 10:13
S8	82	(guidewire stent) and clad \$ with titanium	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/01/06 10:14
S9	228589	(clad composite stent).ti.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/01/06 10:14
S10	11	(clad and composite and stent).ti.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/01/06 10:15
S11	194	clad and guidewire	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/01/06 10:15

S12	3	clad with guidewire	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/01/06 10:16
S13	97	guidewire and clad\$ same (coil helical spring)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/01/06 10:17
S14	60	guidewire and clad\$ with (coil helical spring)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/01/06 10:17
S15	5211036	guidewire and clad\$ near \$3 (coil helical spring)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/01/06 10:17
S16	42	guidewire and clad\$ with wire with (coil helical spring)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/01/06 10:18
S17	7	guidewire and clad\$ with wire with (coil helical spring) and @ad<"20030825"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/01/06 11:04
S19	50	guidewire and taper and coil and (rectangl\$3 near \$3 (cross and section\$3)) and clad	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/01/06 11:05
S20	281	("20030069521" "2524661" "3196876" "3335443" "3466166" "3528410" "3558066" "3562024" "3584327" "3589363" "3605750" "3618594" "3618614" "3749086" "3805787" "3823717" "3830240" "3861391" "3896811" "3930173" "3941122" "3942519" "3956826" "4003369" "4023557" "4041931" "4178935" "4188952" "4202349" "4281419" "4295464" "4345602" "4351326" "4370131" "4380574" "4406284" "4417578" "4425115" "4425908" "4464176" "4465481" "4474180" "4486680" "4504268" "4517793" "4518444" "4535759" "4538622" "4553545" "4561438" "4572184" "4577637" "4580568"	US-PGPUB; USPAT; USOCR	OR	ON	2006/01/06 11:12

"4600446"	"4602633"
"4615331"	"4654092"
"4655771"	"4657024"
"4676249"	"4681110"
"4692139"	"4697595"
"4698058"	"4706681"
"4719916"	"4724846"
"4731084"	"4732152"
"4733665"	"4748971"
"4748986"	"4750488"
"4750902"	"4751916"
"4760849"	"4768507"
"4770664"	"4771773"
"4793348"	"4796637"
"4800890"	"4808246"
"4816018"	"4817600"
"4819618"	"4823793"
"4830003"	"4830023"
"4830262"	"4834747"
"4842590"	"4846186"
"4848343"	"4848348"
"4850999"	"4854330"
"4856516"	"4867173"
"4870953"	"4875480"
"4883486"	"4884579"
"4886062"	"4895168"
"4899733"	"4906241"
"4907572"	"4917104"
"4920954"	"4922905"
"4922923"	"4922924"
"4925445"	"4932419"
"4934380"	"4936845"
"4950227"	"4953553"
"4954126"	"4957110"
"4964409"	"4969891"
"4971490")	.PN. OR
("4980964"	"4984581"
"4989608"	"4990151"
"4991602"	"4995878"
"5001825"	"5003987"
"5003989"	"5012797"
"5015183"	"5015253"
"5019085"	"5019090"
"5024232"	"5024617"
"5025799"	"5026377"
"5040283"	"5046428"
"5047050"	"5052407"
"5059166"	"5061273"
"5061275"	"5064435"
"5067489"	"5069217"
"5069226"	"5071407"
"5077352"	"5084022"
"5092877"	"5095915"
"5104404"	"5109830"
"5111829"	"5117838"
"5129890"	"5135503"
"5139480"	"5144959"
"5147317"	"5147385"

"5152777"	"5160790"
"5163433"	"5163952"
"5171233"	"5171262"
"5171383"	"5176617"
"5179174"	"5197978"
"5201901"	"5207706"
"5213111"	"5217483"
"5230348"	"5238004"
"5251640"	"5253653"
"5256158"	"5256764"
"5276455"	"5290585"
"5304140"	"5320100"
"5333620"	"5334201"
"5341818"	"5345945"
"5354309"	"5360442"
"5365942"	"5366504"
"5368661"	"5372144"
"5373856"	"5374261"
"5382259"	"5389106"
"5433200"	"5451209"
"5452726"	"5464023"
"5474563"	"5476508"
"5489277"	"5496330"
"5498236"	"5506059"
"5514154"	"5516336"
"5520194"	"5531788"
"5556413"	"5588443"
"5607463"	"5609629"
"5628787"	"5630840"
"5636641"	"5637089"
"5645082"	"5647127"
"5647858"	"5658296"
"5664580"	"5695111"
"5701911"	"5706826"
"5720300"	"5724989"
"5725549"	"5725570"
"5725572"	"5733326"
"5749837"	"5769796"
"5772609"	"5788654"
"5797857"	"5807324"
"5813996")	.PN. OR
("5824056"	"5824077"
"5827201"	"5843163"
"5843166"	"5858556"
"5879382"	"5891191"
"5902332"	"5951494"
"6001068"	"6019736"
"6056702"	"6139510"
"6165140"	"6186978"
"6203568"	"6387060"
"6475209"	"6491648"
"6544197")	.PN. OR
("2002/0193706"	
"2003/0060731"	
"2003/0100847"	
"2003/0125641"	
"2004/0039307"	
"2004/0106878"	

		"2004/0122340" "2004/0123915" "6451026" "6461311" "6497709" "6679853" "6740050" "6805676"). URPN.				
S21	265	S20 and @ad<"20030825"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/01/06 11:13
S22	278	S20 and @pd<"20030825"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/01/06 11:14
S23	274	S20 and @pd<"20020825"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/01/06 11:15
S24	133	S20 and @pd<"20020825" and coil	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/01/06 11:15
S25	90	US-5373619-\$.DID. OR US-5957865-\$.DID. OR US-6171338-\$.DID. OR US-3174851-\$.DID. OR US-3351463-\$.DID. OR US-3753700-\$.DID. OR US-3973556-\$.DID. OR US-4080706-\$.DID. OR US-5052404-\$.DID. OR US-5107852-\$.DID. OR US-5211183-\$.DID. OR US-5213111-\$.DID. OR US-5238004-\$.DID. OR US-5409015-\$.DID. OR US-5437288-\$.DID. OR US-5452726-\$.DID. OR US-5477856-\$.DID. OR US-5573520-\$.DID. OR US-5722424-\$.DID. OR US-5741429-\$.DID. OR US-5749837-\$.DID. OR US-5769796-\$.DID. OR US-5772609-\$.DID. OR US-5797857-\$.DID. OR US-5827201-\$.DID. OR US-5836893-\$.DID. OR US-5924998-\$.DID. OR US-5951494-\$.DID. OR US-6001068-\$.DID. OR US-6019736-\$.DID. OR US-6059771-\$.DID. OR US-6139510-\$.DID. OR US-6165140-\$.DID. OR US-6165292-\$.DID. OR	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/01/06 13:10

		US-6329069-\$.DID. OR US-6368316-\$.DID. OR US-6379369-\$.DID. OR US-6428489-\$.DID. OR US-6488637-\$.DID. OR US-6508803-\$.DID. OR US-6544197-\$.DID. OR "20020013540" OR "20020072689" OR "20030069520" OR "20030069521"				
S26	1530	600/585.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/06/14 13:14
S27	1616	guidewire and taper and coil and (rectangl\$3 near \$3 (cross and section\$3))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/06/14 13:14
S28	36	(US-20040039307-\$ or US- 20040122340-\$ or US- 20040106878-\$ or US- 20030100847-\$ or US- 20030060731-\$ or US- 20020072689-\$ or US- 20020058888-\$ or US- 20040123915-\$ or US- 20020043118-\$ or US- 20030125641-\$ or US- 20020193706-\$).did. or (US-6329069-\$ or US- 5573520-\$ or US-5724989- \$ or US-6139510-\$ or US- 6056702-\$ or US-5749837- \$ or US-5147317-\$ or US- 5144959-\$ or US-4003369- \$ or US-6387060-\$ or US- 6451026-\$ or US-5201754- \$ or US-4724846-\$ or US- 6461311-\$ or US-5824077- \$ or US-5800511-\$ or US- 6497709-\$ or US-5772609- \$ or US-5769796-\$ or US- 5827201-\$ or US-5938623- \$ or US-6679853-\$ or US- 6740050-\$ or US-6805676- \$).did. or (EP-386921-\$). did.	US-PGPUB; USPAT; DERWENT	OR	ON	2006/06/14 13:14
S29	0	"10647613"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/22 14:06

S30	1	"10/647613"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/22 14:06
-----	---	-------------	---	----	----	---------------------

8/ 18/ 2009 10:13:24 AM

C:\ Documents and Settings\ jhoekstra\ My Documents\ EAST\ Workspaces\ 10647613\ 01.wsp